



101 749 964

C9C
0

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 6,942,508

Issued: Sep. 13, 2005

Name of Patentee: Wong

Title of Invention: Electrical Adapter

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

Certificate
AUG 02 2006
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR
(a) APPLICANT'S MISTAKE (37 C.F.R. § 1.323) and
(b) PTO MISTAKE (37 C.F.R. § 1.323)

Sir:

1(a). It is noted that three errors appear in this patent of a typographical nature or character, as more fully described below. They occurred in good faith. The word "cord" was misspelled as "card" in three claims (claims 3, 4 and 10). Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination.

1(b). Errors appear in three claims (claims 6, 7 and 20).

2. Attached in duplicate is Form PTO-1050 with at least one copy being suitable for printing.

I hereby certify that this correspondence is being deposited on the date given below with the United States Postal Service as first class mail in an envelope addressed to "Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450."

Date: 7-26-2006

Guy D. Yate, Reg. No. 29,125

03/01/2006 RETURNED 00000002 6542300

01 FC0001

100.00 CP

1

AUG 03 2006

3. The exact locations where the errors occur in the application file are:

(a)(i) Claim 3, column 4, line 67, "power card" should read "power cord."

(a)(ii) Claim 4, column 5, lines 10-11, "power card" should read "power cord."

(a)(iii) Claim 10, column 6, line 3, "power card" should read "power cord."

(b)(i) With respect to the error in claim 6, column 5, lines 30-31, the correct text appears in line 5 of claim 6 on page 4 of the Response to Office Action mailed April 7, 2005.

(b)(ii) With respect to the error in claim 7, column 5, line 43, the correct text appears in line 2 of claim 7 on page 4 of the Response to Office Action mailed April 7, 2005.

(b)(iii) With respect to the error in claim 16, column 8, line 3, the correct text appears in line 11 of claim 20 on page 8 of the Response to Office Action mailed April 7, 2005.

4. Please send the Certificate to:

Alix, Yale & Ristas, LLP
750 Main Street
Hartford, CT 06103

5. Please pay the fee required by 35 C.F.R. §1.20(a) -- \$100.00 as follows:
A check in the amount of \$100.00 is attached. Charge any additional fees or credit
any overpayment to Deposit Account No. 16-2563. A duplicate of this paper is
attached.

Respectfully submitted,

WONG

By

Guy D. Yale

Registration No. 29,125

Alix, Yale & Ristas, LLP

Attorney for Applicant

Date: 7-26-2006
750 Main Street
Hartford, CT 06103-2721
(860) 527-9211
Our Ref: MCHK/148/US
GDY:kcs

\\Fs1\apps\wong\GDY\MCHK148USResDir\Col\P108A1195 - 11a.doc

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,942,508
DATED : Sep. 13, 2005
INVENTOR(S) : Wong

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4:

Line 67, after "power" delete "card" and substitute --cord--.

Column 5:

Lines 10-11, after "power" delete "card" and substitute --cord--.

Lines 30-31, delete "connection" and substitute --connecting--.

Line 43, delete "connection" and substitute --connecting--.

Column 6:

Line 3, after "power" delete "card" and substitute --cord--.

Column 8:

Line 3, delete "requires" and substitute --requires--.

MAILING ADDRESS OF SENDER:
Alix, Yale and Ristas, LLP
750 Main Street
Hartford, CT 06103-2721

PATENT NO. 6,942,508

No. of Additional Copies



Burden Hour Statement: This form is estimated to take 1 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

AUG 03 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,942,508
DATED : Sep. 13, 2005
INVENTOR(S) : Wong

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 4:

Line 67, after "power" delete "card" and substitute --cord--.

Column 5:

Lines 10-11, after "power" delete "card" and substitute --cord--.

Lines 30-31, delete "connection" and substitute --connecting--.

Line 43, delete "connection" and substitute --connecting--.

Column 6:

Line 3, after "power" delete "card" and substitute --cord--.

Column 8:

Line 3, delete "requires" and substitute --requires--.

MAILING ADDRESS OF SENDER:
Alix, Yale and Ristas, LLP
750 Main Street
Hartford, CT 06103-2721

PATENT NO. 6,942,508

No. of Additional Copies



Burden Hour Statement: This form is estimated to take 1 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

2005 09 20